

AMENDMENT OF SOLICITATION/MODIFICATION OF CONTRACT		1. CONTRACT ID CODE		PAGE OF PAGES 1 3	
2. AMENDMENT/MODIFICATION NO. A0003		3. EFFECTIVE DATE 01/04/2006		4. REQUISITION/PURCHASE REQ. NO.	
5. PROJECT NO. (If applicable)		6. ISSUED BY CODE DTS-852		7. ADMINISTERED BY (If other than Item 6) CODE DTS-852	
USDOT/RITA/Volpe Center 55 Broadway Cambridge MA 02142		U.S. DOT/RITA/Volpe Center 55 Broadway Cambridge MA 02142			
8. NAME AND ADDRESS OF CONTRACTOR (No., street, county, State and ZIP Code)		(x) 9A. AMENDMENT OF SOLICITATION NO. DTRT57-06-R-20003			
		X 9B. DATED (SEE ITEM 11) 11/22/2005			
		10A. MODIFICATION OF CONTRACT/ORDER NO.			
		10B. DATED (SEE ITEM 11)			
CODE		FACILITY CODE			

11. THIS ITEM ONLY APPLIES TO AMENDMENTS OF SOLICITATIONS

☒ The above numbered solicitation is amended as set forth in Item 14. The hour and date specified for receipt of Offers ☐ is extended. ☒ is not extended.
Offers must acknowledge receipt of this amendment prior to the hour and date specified in the solicitation or as amended, by one of the following methods: (a) By completing Items 8 and 15, and returning 3 copies of the amendment; (b) By acknowledging receipt of this amendment on each copy of the offer submitted; or (c) By separate letter or telegram which includes a reference to the solicitation and amendment numbers. FAILURE OF YOUR ACKNOWLEDGEMENT TO BE RECEIVED AT THE PLACE DESIGNATED FOR THE RECEIPT OF OFFERS PRIOR TO THE HOUR AND DATE SPECIFIED MAY RESULT IN REJECTION OF YOUR OFFER. If by virtue of this amendment you desire to change an offer already submitted, such change may be made by telegram or letter, provided each telegram or letter makes reference to the solicitation and this amendment, and is received prior to the opening hour and date specified.

12. ACCOUNTING AND APPROPRIATION DATA (If required)

13. THIS ITEM ONLY APPLIES TO MODIFICATION OF CONTRACTS/ORDERS. IT MODIFIES THE CONTRACT/ORDER NO. AS DESCRIBED IN ITEM 14.

CHECK ONE	A. THIS CHANGE ORDER IS ISSUED PURSUANT TO: (Specify authority) THE CHANGES SET FORTH IN ITEM 14 ARE MADE IN THE CONTRACT ORDER NO. IN ITEM 10A.
	B. THE ABOVE NUMBERED CONTRACT/ORDER IS MODIFIED TO REFLECT THE ADMINISTRATIVE CHANGES (such as changes in paying office, appropriation date, etc.) SET FORTH IN ITEM 14, PURSUANT TO THE AUTHORITY OF FAR 43.103(b).
	C. THIS SUPPLEMENTAL AGREEMENT IS ENTERED INTO PURSUANT TO AUTHORITY OF:
	D. OTHER (Specify type of modification and authority)

E. IMPORTANT: Contractor ☐ is not. ☐ is required to sign this document and return _____ copies to the issuing office.

14. DESCRIPTION OF AMENDMENT/MODIFICATION (Organized by UCF section headings, including solicitation/contract subject matter where feasible.)

See the attached continuation sheets for details.

Please acknowledge receipt of this Amendment with the submission of your proposal.

Except as provided herein, all terms and conditions of the document referenced in Item 9A or 10A, as heretofore changed, remains unchanged and in full force and effect.

15A. NAME AND TITLE OF SIGNER (Type or print)		16A. NAME AND TITLE OF CONTRACTING OFFICER (Type or print) Elizabeth A. Segal	
15B. CONTRACTOR/OFFEROR (Signature of person authorized to sign)	15C. DATE SIGNED	16B. UNITED STATES OF AMERICA (Signature of Contracting Officer)	16C. DATE SIGNED

1. The following questions, with corresponding answers, were received in response to the solicitation:

A. Fire Alarm System Specifications, Section 13852

Question 1: Section 13852, 1.02.B.1.a. Complete fire alarm system point list (or copy of CSGM software database) to aid in determination of total available device points.

Answer: Information pending from the FAA.

Question 2: Section 13852, 1.02.B.1.b. Copy of original installation plans showing installed speaker tap settings for determination of available amplifier power requirements.

Answer: Information pending from the FAA.

Question 3: Section 13852, 1.02.B.1.j. Is the elevator un-safe annunciator (assumed to be firefighter's hat symbol) existing?

Answer: Information pending from the FAA

Question 4: Section 13852, 1.02.B.1.m. Please provide applicable model number of desired Addressable Radionics Radio Fire Alarm Transceiver. Is the purpose of radio panel replacement for reliability, compatibility, or additional signal information transmission? If additional signal transmission (above and beyond current fire alarm panel alarm, supervisory, and trouble conditions) is desired please specify type and quantity of signals for estimation of necessary fire panel control modules and programming.

Answer: The purpose of the new Addressable Radionics Transceiver is to take advantage of the new Class A addressable system that will be utilized in the tower as well as to transmit point address information of the existing base building (and tower) systems to the Hickam AFB Fire Department dispatch center. The model number of the new Radionics Radio Fire Alarm Transceiver is: *(Awaiting reply from Hickam Air Force Base Fire Department)*

Question 5: Section 13852, 1.02.B.1.m. Please provide applicable model number of existing Hickam AFB Fire Department Radio Fire Alarm Receiver for verification of communication protocol compatibility and additional signal capability.

Answer: The model number of the existing Radionics Radio Fire Alarm Transceiver is: *(Awaiting reply from Hickam Air Force Base Fire Department)*

Question 6: Section 13852, 2.20. Please specify minimum fault isolator module installation locations (one fault isolator module per signaling line loop is assumed otherwise).

That is an appropriate assumption. One fault isolator module per signaling line loop is sufficient.

B. Fire Alarm System Drawings dated 10/28/05

Question 1: Sheet FLS-HNL8, Note A. Please identify current elevator service provider for coordination of elevator tie-in and operations. Hawaiian Pacific Elevator (HP Elevator) apparently is no longer in existence.

Answer: The Volpe Center will request this information directly from the site.

Question 2: Sheet FLS-HNL8. No heat detector is shown in elevator machine room as required for elevator shunt trip operation per Section 13852, 2.06.B.

Answer: Install a new compatible heat detector below the suspended ceiling for shunt trip purposes.

Question 3: Sheet FLS-HNL10. Riser diagram shows existing stairwell smoke detectors on levels 2 through 8. Only level 4 has an existing stairwell smoke detector. Please clarify if new detectors will be required for this stairwell at all levels.

Answer: Detectors will need to be placed at all levels of the stairwell.

C. General Questions

Question 1: Reprogramming of the existing MXLV (addressable Siemens/Pyrotronics) fire alarm control panel will require that the panel owner, in this case the FAA, submit a written request to Siemens allowing for a non-installing system vendor to gain access to internal programming software. This procedure will take approximately six weeks to complete. Please verify that owner is willing to make this request. Application forms can be provided upon request.

Answer: The Owner understands the design intent and will request information as needed from the original installer to accomplish this Statement of Work. Provide requests for necessary information immediately upon Award of Contract. In addition, the requestor is reminded that qualified individuals are required to serve specific roles for the project. Specification 13852 Section 1.02.D states "System configuration, installation, programming and testing shall be supervised by a National Institute for Certification in Engineering Technologies (NICET) Level III (or IV) Fire Alarm Engineering Technician, trained by the manufacturer of the fire alarm system to be installed." Further, Section 1.02.E requires the job site supervisor to be minimum NICET Level III and "manufacturer trained" on the system being installed. If the requestor's personnel are not so qualified, the Volpe Center will consider accepting the qualifications of a suitable sub-contractor to meet the project requirements.

2. All other terms and conditions of the solicitation remain unchanged.